

PeakTech® 2530

PROD-ID: P 2530

[BACK](#)

3-Phase Rotation Tester with LCD-display

New handheld tester designed according to safety standard CAT III 600 V in modern, compact style for checking phase sequence and rotation. LCD-Displays provided on the unit will show whether the phase is open or which phase in open at a glance.

- Robust alligator clips for easy connection
- Application in 3-phase power sources from 40 ... 690 V AC
- No battery required
- Safety: EN 61010-1; CAT III 600 V; type of protection IP-40
- Accessories: test leads, alligator clips, carrying case and operation manual



MANUAL

[PeakTech_2530.pdf \(345.4 kB\)](#)

PICTURES

[2530 L.jpg \(316.7 kB\)](#)

[2530 R.jpg \(328.5 kB\)](#)

Measuring voltage range	40 ... 690 V AC
Frequency range	15 ... 400 Hz
Test current	1 mA/phase
Current pickup	1 mA
Dimensions (WxHxD)	70 x 130 x 32 mm
Weight	130 g
EAN-13	4250569400483

